SSM 52242 2024 Mustang - DTC U211B:87 Setting In The Anti-Lock Brake System (ABS) Module When A Diagnostic Self Test Is Performed

Some 2024 Mustang vehicles may set diagnostic trouble code (DTC) U211B:87 in the ABS module during a diagnostic self-test. This may be due to the ABS module's DTC sensitivity during vehicle key-on/start-up. To correct the condition, reprogram the ABS module using the latest software level of the Ford Diagnosis and Repair System (FDRS) diagnostic scan tool. For claiming, use the causal part number 2005 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.