



The 2024 Ford Mustang has a Technical Service Bulletin (TSB) addressing water intrusion issues, particularly related to the body control module (BCM) and connectors. This TSB outlines inspection and potential replacement procedures if water is detected in the BCM area.  The Truth About Cars  [mustang7g.com](https://mustang7g.com)

## Overview of the 2024 Ford Mustang TSB on Water Intrusion

The 2024 Ford Mustang has a Technical Service Bulletin (TSB) that specifically addresses issues related to water intrusion. This TSB is crucial for ensuring the reliability and safety of the vehicle.

### Key Details of the TSB

- **Focus:** The TSB primarily concerns the body control module (BCM) and its connectors.
- **Inspection Procedures:** The bulletin outlines steps for inspecting the BCM area for water intrusion.
- **Remedial Actions:** If water is detected, the TSB recommends replacing the BCM to prevent further issues.

### Importance of the TSB

Water intrusion can lead to various electrical problems, including malfunctioning lights and potential battery drainage. Addressing these issues promptly is essential for maintaining vehicle performance and safety.

### Summary Table of TSB Actions

Action	Description
Inspection	Check BCM and connectors for water intrusion.
Replacement	Replace BCM if water is detected.
Preventive Measures	Follow guidelines to seal potential leak areas.

This TSB is part of Ford's ongoing efforts to address and rectify common issues in their vehicles, ensuring a better ownership experience for Mustang drivers.