

Last Vehicle Status Update: 11-July-2024 11:59 AM

*Note: Do not use as a pressure gauge

Refresh

Odometer



326 Miles

Fuel Level



Fuel Level: 10%

Fuel Range: 27 Miles to empty

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)
Front : 32 | Rear : 32

Oil Life Remaining



99%

12V Battery



Battery State of Charge : 81%
 Battery Voltage : 13.7V

60-Day VHA/DTC History

Last Vehicle Health Update: 11-July-2024 11:44 PM

May 2024

Sun	Mon	Tue	Wed	Thu
			1	2
5	6	7	8	9
12	13	14	15	16
19	20	21	22	23
26	27	28	29	30

June 2024

Sun	Mon	Tue	Wed	Thu
2	3	4	5	6
9	10	11	12	13
16	17	18	19	20
23	24	25	26	27
30				

July 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15	16	17	18
21	22	23	24	25
28	29	30	31	

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date | Time | Odometer

Event Description

Module

DTC

FT : SB

TSB/GSB/SSM



Send to Search

Description

Time : 11:03 AMOdometer :
306 mi

GWM		U2404:0A : 48
ABS		U023A:87 : AF
RCM		B00D5:14 : 28
PCM		U0104:00 : 2F
HCM		C1A03:29 : 08
ABS		U211B:08 : 2F
PCM		U023A:00 : 2E
TCU		U0146:09 : 08
RCM		B1202:14 : 28
HCM		C1A05:29 : 08

<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Lost Communication With Cruise Control Module
<input type="checkbox"/>		Left Front Height Sensor
<input type="checkbox"/>		Control Module Message Authentication
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>		Restraint System Passenger Enable Indicator
<input type="checkbox"/>		Left Rear Height Sensor

Time : 10:41 AMOdometer :
296 mi

GWM		U2404:0A : 48
ABS		U023A:87 : AF
RCM		B00D5:14 : 28
PCM		U0104:00 : 2F
HCM		C1A03:29 : 08
ABS		U211B:08 : 2F
PCM		U023A:00 : 2E
TCU		U0146:09 : 08
RCM		B1202:14 : 28
HCM		C1A05:29 : 08








<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Lost Communication With Cruise Control Module
<input type="checkbox"/>		Left Front Height Sensor
<input type="checkbox"/>		Control Module Message Authentication
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>		Restraint System Passenger Enable Indicator
<input type="checkbox"/>		Left Rear Height Sensor

Time : 07:59 AMOdometer :
272 mi

GWM		U2404:0A : 48
ABS		U023A:87 : AF
RCM		B00D5:14 : 28
LDCMA		U3003:16 : 28
PCM		U0104:00 : 2F













<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Cruise Control Module

HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08

-  Left Front Height Sensor
-  Control Module Message Authentication
-  Battery Voltage
-  Lost Communication With Image Processing Module 'A'
-  Lost Communication With Serial Data Gateway Module 'A'
-  Restraint System Passenger Enable Indicator
-  Left Rear Height Sensor










Time : 07:36 AM
Odometer :
268 mi



GWM | U2404: 0A : 48
ABS | U023A: 87 : AF
RCM | B00D5: 14 : 28
LDCMA | U3003: 16 : 28
PCM | U0104: 00 : 2F
HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08

-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Disable Indicator
-  Battery Voltage
-  Lost Communication With Cruise Control Module
-  Left Front Height Sensor
-  Control Module Message Authentication
-  Battery Voltage
-  Lost Communication With Image Processing Module 'A'
-  Lost Communication With Serial Data Gateway Module 'A'
-  Restraint System Passenger Enable Indicator
-  Left Rear Height Sensor

Time : 07:14 AM
Odometer :
257 mi

GWM | U2404: 0A : 48
ABS | U023A: 87 : AF
RCM | B00D5: 14 : 28
LDCMA | U3003: 16 : 28
PCM | U0104: 00 : 2F
HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E













-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Disable Indicator
-  Battery Voltage
-  Lost Communication With Cruise Control Module
-  Left Front Height Sensor
-  Control Module Message Authentication
-  Battery Voltage
-  Lost Communication With Image Processing Module 'A'

TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor

Time : 06:03 AM

Odometer :













257 mi

GWM		U2404: 0A : 48	<input type="checkbox"/>  Ethernet Failure With Image Processing Module 'A' (IPMA)
ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module
HCM		C1A03: 29 : 08	<input type="checkbox"/>  Left Front Height Sensor
ABS		U211B: 08 : 2F	<input type="checkbox"/>  Control Module Message Authentication
LDCMB		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
PCM		U023A: 00 : 2E	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor

Time : 02:39 AM

Odometer :

251 mi













GWM		U2404: 0A : 48	<input type="checkbox"/>  Ethernet Failure With Image Processing Module 'A' (IPMA)
ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module
HCM		C1A03: 29 : 08	<input type="checkbox"/>  Left Front Height Sensor
ABS		U211B: 08 : 2F	<input type="checkbox"/>  Control Module Message Authentication
LDCMB		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U023A: 00 : 2E	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor

Time : 02:24 AM

Odometer :

250 mi

GWM		U2404:0A : 48
ABS		U023A: 87 : AF
RCM		B00D5: 14 : 28
LDCMA		U3003: 16 : 28
PCM		U0104: 00 : 2F
HCM		C1A03: 29 : 08
ABS		U211B: 08 : 2F
LDCMB		U3003: 16 : 28
PCM		U023A: 00 : 2E
TCU		U0146: 09 : 08
RCM		B1202: 14 : 28
HCM		C1A05: 29 : 08

-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Disable Indicator
-  Battery Voltage
-  Lost Communication With Cruise Control Module
-  Left Front Height Sensor
-  Control Module Message Authentication
-  Battery Voltage
-  Lost Communication With Image Processing Module 'A'
-  Lost Communication With Serial Data Gateway Module 'A'
-  Restraint System Passenger Enable Indicator
-  Left Rear Height Sensor

Time : 12:17 PMOdometer :
249 mi

GWM		U2404:0A : 48
ABS		U023A: 87 : AF
RCM		B00D5: 14 : 28
LDCMA		U3003: 16 : 28
PCM		U0104: 00 : 2F
HCM		C1A03: 29 : 08
ABS		U211B: 08 : 2F
LDCMB		U3003: 16 : 28
PCM		U023A: 00 : 2E
TCU		U0146: 09 : 08
RCM		B1202: 14 : 28
HCM		C1A05: 29 : 08

<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Cruise Control Module
<input type="checkbox"/>		Left Front Height Sensor
<input type="checkbox"/>		Control Module Message Authentication
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>		Restraint System Passenger Enable Indicator
<input type="checkbox"/>		Left Rear Height Sensor

Time : 12:04 PMOdometer :
244 mi












GWM		U2404:0A : 48
ABS		U023A: 87 : AF
RCM		B00D5: 14 : 28
LDCMA		U3003: 16 : 28
PCM		U0104: 00 : 2F
HCM		C1A03: 29 : 08
ABS		U211B: 08 : 2F
LDCMB		U3003: 16 : 28
TCU		U0146: 09 : 08
PCM		U023A: 00 : 2E
RCM		B1202: 14 : 28
HCM		C1A05: 29 : 08

<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Cruise Control Module
<input type="checkbox"/>		Left Front Height Sensor
<input type="checkbox"/>		Control Module Message Authentication
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Enable Indicator
<input type="checkbox"/>		Left Rear Height Sensor













Time : 11:18 AMOdometer :
238 mi

GWM		U2404:0A : 48
-----	--	---------------






<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
--------------------------	--	--

ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module
HCM		C1A03: 29 : 08	<input type="checkbox"/>  Left Front Height Sensor
ABS		U211B: 08 : 2F	<input type="checkbox"/>  Control Module Message Authentication
LDCMB		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U023A: 00 : 2E	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor








Time : 07:58 AM
Odometer :
 221 mi

GWM		U2404: 0A : 48	<input type="checkbox"/>  Ethernet Failure With Image Processing Module 'A' (IPMA)
ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module
HCM		C1A03: 29 : 08	<input type="checkbox"/>  Left Front Height Sensor
ABS		U211B: 08 : 2F	<input type="checkbox"/>  Control Module Message Authentication
LDCMB		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U023A: 00 : 2E	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor

Time : 06:31 AM
Odometer :
 211 mi













GWM		U2404: 0A : 48	<input type="checkbox"/>  Ethernet Failure With Image Processing Module 'A' (IPMA)
ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module

HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08

 Left Front Height Sensor
  Control Module Message Authentication
  Battery Voltage
  Lost Communication With Image Processing Module 'A'
  Lost Communication With Serial Data Gateway Module 'A'
  Restraint System Passenger Enable Indicator
  Left Rear Height Sensor









Time : 04:08 AM
Odometer :
157 mi

GWM | U2404: 0A : 48
ABS | U023A: 87 : AF
RCM | B00D5: 14 : 28
LDCMA | U3003: 16 : 28
PCM | U0104: 00 : 2F
HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08





 Ethernet Failure With Image Processing Module 'A' (IPMA)
  Lost Communication With Image Processing Module 'A'
  Restraint System Passenger Disable Indicator
  Battery Voltage
  Lost Communication With Cruise Control Module
  Left Front Height Sensor
  Control Module Message Authentication
  Battery Voltage
  Lost Communication With Image Processing Module 'A'
  Lost Communication With Serial Data Gateway Module 'A'
  Restraint System Passenger Enable Indicator
  Left Rear Height Sensor

Time : 03:12 AM
Odometer :
149 mi

HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08
GWM | U2404: 0A : 48













 Left Front Height Sensor
  Control Module Message Authentication
  Battery Voltage
  Lost Communication With Image Processing Module 'A'
  Lost Communication With Serial Data Gateway Module 'A'
  Restraint System Passenger Enable Indicator
  Left Rear Height Sensor
  Ethernet Failure With Image Processing Module 'A' (IPMA)

ABS | U023A: 87 : AF
RCM | B00D5: 14 : 28
LDCMA | U3003: 16 : 28
PCM | U0104: 00 : 2F

 Lost Communication With Image Processing Module 'A'
  Restraint System Passenger Disable Indicator
  Battery Voltage
  Lost Communication With Cruise Control Module













Time : 03:10 AM
Odometer :
149 mi

GWM | U2404: 0A : 48
ABS | U023A: 87 : AF
RCM | B00D5: 14 : 28
LDCMA | U3003: 16 : 28
PCM | U0104: 00 : 2F
HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08

 Ethernet Failure With Image Processing Module 'A' (IPMA)
  Lost Communication With Image Processing Module 'A'
  Restraint System Passenger Disable Indicator
  Battery Voltage
  Lost Communication With Cruise Control Module
  Left Front Height Sensor
  Control Module Message Authentication
  Battery Voltage
  Lost Communication With Image Processing Module 'A'
  Lost Communication With Serial Data Gateway Module 'A'
  Restraint System Passenger Enable Indicator
  Left Rear Height Sensor

Time : 02:51 AM
Odometer :
134 mi

GWM | U2404: 0A : 48
ABS | U023A: 87 : AF
RCM | B00D5: 14 : 28
LDCMA | U3003: 16 : 28
PCM | U0104: 00 : 2F
HCM | C1A03: 29 : 08
ABS | U211B: 08 : 2F
LDCMB | U3003: 16 : 28
PCM | U023A: 00 : 2E
TCU | U0146: 09 : 08
RCM | B1202: 14 : 28
HCM | C1A05: 29 : 08


 Ethernet Failure With Image Processing Module 'A' (IPMA)
  Lost Communication With Image Processing Module 'A'
  Restraint System Passenger Disable Indicator
  Battery Voltage
  Lost Communication With Cruise Control Module
  Left Front Height Sensor
  Control Module Message Authentication
  Battery Voltage
  Lost Communication With Image Processing Module 'A'
  Lost Communication With Serial Data Gateway Module 'A'
  Restraint System Passenger Enable Indicator
  Left Rear Height Sensor

Time : 02:16 AM


Odometer :

123 mi

GWM | U2404:0A :48

 Ethernet Failure With Image Processing Module 'A' (IPMA)

ABS | U023A:87 :AF

 Lost Communication With Image Processing Module 'A'


RCM | B00D5:14 :28

 Restraint System Passenger Disable Indicator


LDCMA | U3003:16 :28

 Battery Voltage


PCM | U0104:00 :2F

 Lost Communication With Cruise Control Module

HCM | C1A03:29 :08

 Left Front Height Sensor


ABS | U211B:08 :2F

 Control Module Message Authentication


LDCMB | U3003:16 :28

 Battery Voltage

PCM | U023A:00 :2E

 Lost Communication With Image Processing Module 'A'

TCU | U0146:09 :08

 Lost Communication With Serial Data Gateway Module 'A'

RCM | B1202:14 :28

 Restraint System Passenger Enable Indicator

HCM | C1A05:29 :08


 Left Rear Height Sensor

Time : 01:50 AM


Odometer :

117 mi

GWM | U2404:0A :48

 Ethernet Failure With Image Processing Module 'A' (IPMA)

ABS | U023A:87 :AF

 Lost Communication With Image Processing Module 'A'

RCM | B00D5:14 :28

 Restraint System Passenger Disable Indicator

LDCMA | U3003:16 :28

 Battery Voltage

PCM | U0104:00 :2F

 Lost Communication With Cruise Control Module

HCM | C1A03:29 :08

 Left Front Height Sensor


ABS | U211B:08 :2F

 Control Module Message Authentication


LDCMB | U3003:16 :28

 Battery Voltage

PCM | U023A:00 :2E

 Lost Communication With Image Processing Module 'A'

TCU | U0146:09 :08

 Lost Communication With Serial Data Gateway Module 'A'

RCM | B1202:14 :28

 Restraint System Passenger Enable Indicator

HCM | C1A05:29 :08

 Left Rear Height Sensor

Time : 12:52 PM

Odometer :
115 mi

GWM		U2404:0A : 48
ABS		U023A: 87 : AF
RCM		B00D5: 14 : 28
LDCMA		U3003: 16 : 28
PCM		U0104: 00 : 2F
HCM		C1A03: 29 : 08
ABS		U211B: 08 : 2F
LDCMB		U3003: 16 : 28
TCU		U0146: 09 : 08
PCM		U023A: 00 : 2E
RCM		B1202: 14 : 28
HCM		C1A05: 29 : 08

<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Cruise Control Module
<input type="checkbox"/>		Left Front Height Sensor
<input type="checkbox"/>		Control Module Message Authentication
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Enable Indicator
<input type="checkbox"/>		Left Rear Height Sensor

Time : 04:13 AM

Odometer :
106 mi

GWM		U2404:0A : 48
ABS		U023A: 87 : AF
RCM		B00D5: 14 : 28
LDCMA		U3003: 16 : 28
PCM		U0104: 00 : 2F
HCM		C1A03: 29 : 08
ABS		U211B: 08 : 2F
LDCMB		U3003: 16 : 28
PCM		U023A: 00 : 2E
TCU		U0146: 09 : 08
RCM		B1202: 14 : 28
HCM		C1A05: 29 : 08












<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Restraint System Passenger Disable Indicator
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Cruise Control Module
<input type="checkbox"/>		Left Front Height Sensor
<input type="checkbox"/>		Control Module Message Authentication
<input type="checkbox"/>		Battery Voltage
<input type="checkbox"/>		Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>		Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>		Restraint System Passenger Enable Indicator
<input type="checkbox"/>		Left Rear Height Sensor

Time : 03:34 AM













Odometer :
101 mi

GWM		U2404:0A : 48
-----	--	---------------






<input type="checkbox"/>		Ethernet Failure With Image Processing Module 'A' (IPMA)
--------------------------	--	--

ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module
HCM		C1A03: 29 : 08	<input type="checkbox"/>  Left Front Height Sensor
ABS		U211B: 08 : 2F	<input type="checkbox"/>  Control Module Message Authentication
LDCMB		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U023A: 00 : 2E	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor








Time : 02:47 AM
Odometer :
86 mi

GWM		U2404: 0A : 48	<input type="checkbox"/>  Ethernet Failure With Image Processing Module 'A' (IPMA)
ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module
HCM		C1A03: 29 : 08	<input type="checkbox"/>  Left Front Height Sensor
ABS		U211B: 08 : 2F	<input type="checkbox"/>  Control Module Message Authentication
LDCMB		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U023A: 00 : 2E	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
TCU		U0146: 09 : 08	<input type="checkbox"/>  Lost Communication With Serial Data Gateway Module 'A'
RCM		B1202: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Enable Indicator
HCM		C1A05: 29 : 08	<input type="checkbox"/>  Left Rear Height Sensor

Time : 01:17 AM
Odometer :
85 mi

GWM		U2404: 0A : 48	<input type="checkbox"/>  Ethernet Failure With Image Processing Module 'A' (IPMA)
ABS		U023A: 87 : AF	<input type="checkbox"/>  Lost Communication With Image Processing Module 'A'
RCM		B00D5: 14 : 28	<input type="checkbox"/>  Restraint System Passenger Disable Indicator
LDCMA		U3003: 16 : 28	<input type="checkbox"/>  Battery Voltage
PCM		U0104: 00 : 2F	<input type="checkbox"/>  Lost Communication With Cruise Control Module

HCM		C1A03: 29 : 08
ABS		U211B: 08 : 2F
LDCMB		U3003: 16 : 28
PCM		U023A: 00 : 2E
TCU		U0146: 09 : 08
RCM		B1202: 14 : 28
HCM		C1A05: 29 : 08

-  Left Front Height Sensor
-  Control Module Message Authentication
-  Battery Voltage
-  Lost Communication With Image Processing Module 'A'
-  Lost Communication With Serial Data Gateway Module 'A'
-  Restraint System Passenger Enable Indicator
-  Left Rear Height Sensor

Time : 12:26 PM

Odometer :
85 mi

★ TCU		U0146: 09 : 08
ABS		U023A: 87 : AF
ABS		U211B: 08 : 2F
GWM		U2404: 0A : 48
HCM		C1A03: 29 : 08
HCM		C1A05: 29 : 08
LDCMA		U3003: 16 : 28
LDCMB		U3003: 16 : 28
PCM		U0104: 00 : 2F
PCM		U023A: 00 : 2E
RCM		B00D5: 14 : 28
RCM		B1202: 14 : 28

<input type="checkbox"/>	⚠	Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>	⚠	Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>	⚠	Control Module Message Authentication
<input type="checkbox"/>	⚠	Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>	⚠	Left Front Height Sensor
<input type="checkbox"/>	⚠	Left Rear Height Sensor
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Lost Communication With Cruise Control Module
<input type="checkbox"/>	⚠	Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>	⚠	Restraint System Passenger Disable Indicator
<input type="checkbox"/>	⚠	Restraint System Passenger Enable Indicator

Time : 11:38 AM

Odometer :
78 mi

★ LDCMA		U3003: 16 : 28
★ LDCMB		U3003: 16 : 28
★ TCU		U0146: 09 : 0A
ABS		U023A: 87 : AF
ABS		U211B: 08 : 2F
GWM		U2404: 0A : 48
HCM		C1A03: 29 : 08
HCM		C1A05: 29 : 08
PCM		U0104: 00 : 2F
PCM		U023A: 00 : 2E
RCM		B00D5: 14 : 28
RCM		B1202: 14 : 28

<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Lost Communication With Serial Data Gateway Module 'A'
<input type="checkbox"/>	⚠	Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>	⚠	Control Module Message Authentication
<input type="checkbox"/>	⚠	Ethernet Failure With Image Processing Module 'A' (IPMA)
<input type="checkbox"/>	⚠	Left Front Height Sensor
<input type="checkbox"/>	⚠	Left Rear Height Sensor
<input type="checkbox"/>	⚠	Lost Communication With Cruise Control Module
<input type="checkbox"/>	⚠	Lost Communication With Image Processing Module 'A'
<input type="checkbox"/>	⚠	Restraint System Passenger Disable Indicator
<input type="checkbox"/>	⚠	Restraint System Passenger Enable Indicator

Time : 01:02 AM

Odometer :
78 mi

★ ABS		U211B: 87 : 28
ABS		U211B: 08 : 2F

SSM

<input type="checkbox"/>	⚠	Control Module Message Authentication
<input type="checkbox"/>	⚠	Control Module Message Authentication

ABS | U023A: 87 : AF

GWM | U2404: 0A : 48

HCM | C1A03: 29 : 08









HCM | C1A05: 29 : 08

PCM | U0104: 00 : 2F

PCM | U023A: 00 : 2E

RCM | B00D5: 14 : 28

RCM | B1202: 14 : 28

-  Lost Communication With Image Processing Module 'A'
-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Left Front Height Sensor
-  Left Rear Height Sensor
-  Lost Communication With Cruise Control Module
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Disable Indicator
-  Restraint System Passenger Enable Indicator

28-June-2024

Time : 01:35 AM
 Odometer :
 70 mi

GWM | U2404: 0A : 48

ABS | U023A: 87 : AF

RCM | B00D5: 14 : 28

PCM | U0104: 00 : 2F










HCM | C1A03: 29 : 08

ABS | U211B: 08 : 2F

PCM | U023A: 00 : 2E

RCM | B1202: 14 : 28

HCM | C1A05: 29 : 08

- Select All**
-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Disable Indicator
-  Lost Communication With Cruise Control Module
-  Left Front Height Sensor
-  Control Module Message Authentication
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Enable Indicator
-  Left Rear Height Sensor

17-June-2024

Select All

Time : 11:21 AM

Odometer :

70 mi

★	HCM		C1A05: 29 : 08
★	HCM		C1A03: 29 : 08
	ABS		U023A: 87 : AF
	ABS		U211B: 08 : 2F
	GWM		U2404: 0A : 48
	PCM		U0104: 00 : 2F
	PCM		U023A: 00 : 2E
	RCM		B00D5: 14 : 28
	RCM		B1202: 14 : 28

- ⚠ Left Rear Height Sensor
- ⚠ Left Front Height Sensor
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Control Module Message Authentication
- ⚠ Ethernet Failure With Image Processing Module 'A' (IPMA)
- ⚠ Lost Communication With Cruise Control Module
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Restraint System Passenger Disable Indicator
- ⚠ Restraint System Passenger Enable Indicator

16-June-2024

Select All

Time : 08:08 AM

Odometer :

69 mi

	GWM		U2404: 0A : 48
	ABS		U023A: 87 : AF
	RCM		B00D5: 14 : 28
	PCM		U0104: 00 : 2F
	ABS		U211B: 08 : 2F
	PCM		U023A: 00 : 2E
	RCM		B1202: 14 : 28

- ⚠ Ethernet Failure With Image Processing Module 'A' (IPMA)
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Restraint System Passenger Disable Indicator
- ⚠ Lost Communication With Cruise Control Module
- ⚠ Control Module Message Authentication
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Restraint System Passenger Enable Indicator

Time : 05:04 AM

Odometer :

69 mi

	GWM		U2404: 0A : 48
	ABS		U023A: 87 : AF
	RCM		B00D5: 14 : 28
	PCM		U0104: 00 : 2F
	ABS		U211B: 08 : 2F
	PCM		U023A: 00 : 2E
	RCM		B1202: 14 : 28

- ⚠ Ethernet Failure With Image Processing Module 'A' (IPMA)
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Restraint System Passenger Disable Indicator
- ⚠ Lost Communication With Cruise Control Module
- ⚠ Control Module Message Authentication
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Restraint System Passenger Enable Indicator

Time : 05:36 AM

Odometer :
69 mi

GWM | U2404:0A :48

ABS | U023A:87 :AF

ABS | U211B:87 :28 SSM









RCM | B00D5:14 :28

PCM | U0104:00 :2F

ABS | U211B:08 :2F

PCM | U023A:00 :2E

RCM | B1202:14 :28

-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Control Module Message Authentication
-  Restraint System Passenger Disable Indicator
-  Lost Communication With Cruise Control Module
-  Control Module Message Authentication
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Enable Indicator

Time : 04:41 AM

Odometer :
14 mi

ABS | U211B:08 :2F

PCM | U023A:00 :2E

RCM | B1202:14 :28









GWM | U2404:0A :48

ABS | U023A:87 :AF

ABS | U211B:87 :28 SSM

RCM | B00D5:14 :28

PCM | U0104:00 :2F

-  Control Module Message Authentication
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Enable Indicator
-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Control Module Message Authentication
-  Restraint System Passenger Disable Indicator
-  Lost Communication With Cruise Control Module

Time : 04:34 AM

Odometer :
14 mi

RCM | B00D5:14 :28

PCM | U0104:00 :2F

ABS | U211B:08 :2F









PCM | U023A:00 :2E

RCM | B1202:14 :28

GWM | U2404:0A :48

ABS | U023A:87 :AF

ABS | U211B:87 :28 SSM

-  Restraint System Passenger Disable Indicator
-  Lost Communication With Cruise Control Module
-  Control Module Message Authentication
-  Lost Communication With Image Processing Module 'A'
-  Restraint System Passenger Enable Indicator
-  Ethernet Failure With Image Processing Module 'A' (IPMA)
-  Lost Communication With Image Processing Module 'A'
-  Control Module Message Authentication

Time : 04:29 AM

Odometer :

13 mi

★	ABS		U211B: 87 : 28
★	RCM		B1202: 14 : 28
★	RCM		B00D5: 14 : 28
	ABS		U023A: 87 : AF
	ABS		U211B: 08 : 2F
	GWM		U2404: 0A : 48
	PCM		U0104: 00 : 2F
	PCM		U023A: 00 : 2E

SSM

- ⚠ Control Module Message Authentication
- ⚠ Restraint System Passenger Enable Indicator
- ⚠ Restraint System Passenger Disable Indicator
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Control Module Message Authentication
- ⚠ Ethernet Failure With Image Processing Module 'A' (IPMA)
- ⚠ Lost Communication With Cruise Control Module
- ⚠ Lost Communication With Image Processing Module 'A'

10-June-2024

Time : 06:27 AM

Odometer :

12 mi

	GWM		U2404: 0A : 48
	ABS		U023A: 87 : AF
	PCM		U0104: 00 : 2F
	ABS		U211B: 08 : 2F
	PCM		U023A: 00 : 2E

Select All

- ⚠ Ethernet Failure With Image Processing Module 'A' (IPMA)
- ⚠ Lost Communication With Image Processing Module 'A'
- ⚠ Lost Communication With Cruise Control Module
- ⚠ Control Module Message Authentication
- ⚠ Lost Communication With Image Processing Module 'A'